UNIT B19.1 Fabric Cutting

Range of Equipment / Machinery: Cutting Machines & Pair of Scissors

Suggested deletion Suggested addition

Competence: Carry out multi-lay fabric cutting

	Criteria	С	NYC
19.1.2 Multi-lay	Checking of Tools and equipment	All tools and equipment are checked to be operational and in required a condition for safe and effective use.	Some or all tools and equipment are not checked to be or are not operational and in required a condition for safe and effective use.
fabric cutting		All faulty equipment and tools are reported to the relevant person, isolated and replaced.	Some or all faulty equipment and tools are not reported to the relevant person, not isolated and/or replaced.
	Preparation of equipment, tools and workstation.	All tools, equipment and workstation are prepared as per work practice or procedure for multi-lay cutting.	All or some tools, equipment and workstation are not prepared as per work practice or procedure for multi-lay cutting.
	Confirming specification	The specification for cutting is checked and confirmed to be clear and complete.	The specification for cutting is not checked and/or confirmed to be clear and complete.
		Any queries regarding the specification are clarified with the relevant person.	Some or all queries regarding the specification are not clarified with the relevant person
	Tool selection	Correct All tools required for the job are selected and set out at the work station.	Some or all tools selected are missing or not required for the job and or not set out at the workstation or according to procedure are incorrect.
	Tools, equipment and work station	All equipment and tools are handled safely and without damage.	Some or all tools are not handled safely and are damaged during use.
	handling	Workstation, equipment and tools are free of lubricants or debris before starting cutting.	Some or all workstation, equipment and tools are not free of lubricants or debris before starting cutting.
	Task preparation	Preparation for the cutting task is performed safely and within the time allocated.	Not all preparation for the cutting task is performed safely or within the allocated time.
	Use of PPE and safety rules	All PPE for the task and machine used correctly and safety rules followed.	Some or none PPE for the task and machine used correctly and or some or none of the safety rules are followed.

Competence: Frame Covering

PC	Criteria	С	NYC
19.1.3	Selecting tools	All correct required tools and components for frame	Some of the tools and components selected are required, some are
Cover	and components	covering are selected. All tools and components are	missing or not required. Some or none tools and components are clean
prepared		clean and in good operational condition.	and in good operational condition.
frame	Performing and	Perform and complete covering operations according	All or some covering operations are not performed according to work
	completing	to work practice procedure and within the given time	practice procedure and/ or completed within the given timeframe of 4
	covering	frame of 4 6 hrs	6hrs
	operations		
	Use of PPE and	All PPE for the task and machine used correctly and	Some or none PPE for the task and machine used correctly and or some
	safety rules	safety rules followed.	or none of the safety rules are followed.

Competence: Sewing Covers on a Machine for upholstered items

PC	Criteria	С	NYC
19.1.4	Selecting	All required materials and equipment selected for the	All or some materials and equipment are selected as required for the
Sewing	materials and	<mark>job.</mark>	<mark>job</mark> .
Covers	equipment		
	Preparing	Correct All required tools, equipment and components	All or some tools, equipment and components are not prepared for
	equipment and	prepared for sewing as per work practice and	sewing as per work practice and procedures.
	components	procedures.	
	Sewing seams	Correct Straight and even sewing of seams completed	All or some of the sawn seams are not incorrectly straight and even
	Sewing Seams	within the range of 15 – 20mm from edge of fabric.	done exceeding the range of 15 – 20mm from edge of fabric.
		within the range of 15 – 2011111 <mark>from edge of fabric</mark> .	done exceeding the range of 13 – 20mm from edge of fabric.
	Assembling	Correct Assembling of covers done within given	Assembling of covers not done within the given specifications
	covers	specifications	
	Attaching	Correct Attachment of ancillary items done within the	All or some attachments of ancillary items not done within the given
	ancillary items	given specifications.	specifications
	Use of PPE and	All PPE for the task and machine used correctly and	Some or none PPE for the task and machine used correctly and or some
	safety rules	safety rules followed.	or none of the safety rules are followed.